

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आज़ादी व अमृत महोत्सव

No. F6/DFS/MS/GH/SZ/2024/ 515

Dated: 26/12/2024

FIRE SAFETY CERTIFICATE

Certified that the Toronto Guest House located at 10072 to 10076, Gali No. 1, Multani Dhanda, Pahar Ganj, New Delhi comprised of Stilt floor, Ground plus three upper floors, Stilt floor (Parking), Ground floor (reception + 04 guest rooms), 1st floor to 3rd floor (05 guest rooms at each floor), total 19 guest rooms was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/NDZ/2022/160 dated 21/03/2022. The premises was re-inspected by the officer concerned of this department on dated 16/12/2024 in presence of Mr. Sanjay Vij (Owner) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential" Sub Division A-1, Ground floor (reception + 04 guest rooms), 1st floor to 3rd floor (05 guest rooms at each floor), total 19 guest rooms up to third floor only as above validity up to 31/03/2027 in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010. Subject to conditions printed below.

Issued on 26 12 2024 at New Delhi by.

(ATUL GARG)
DIRECTOR
OF DELHI FIRE SERVICE

Copy to:-

- 1. The Commission, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- Mr. Sanjay Vij (Owner), Toronto Guest House, 10072 to 10076, Gali No. 1, Multani Dhanda, Pahar Ganj, New Delhi.
- The Joint Commissioner of police (Lic.), Ist Floor, P.S Defence Colony, New Delhi-24 w.e.f. MHA portal ID - 2024120917807 dated 09/12/2024.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

			CTION REPORT				
1	Na	me & address of the building	Toronto Guest House located at 10072 to 10076 Gali No. 1, Multani Dhanda, Pahar Ganj, Nev Delhi.				
2	Bu	ilding is comprised of	Stilt, Gr. + 3 upper floors (Total 19 Guest rooms) Ground floor (reception + 04 guest rooms), 1 st floor to 3 rd floor (05 guest rooms at each floor)				
3	Ty	pe of occupancy	Residential, Sub Division-A-1				
4		pe of case	Renewal				
5		tails of previous FSC	F6/DFS/MS/GH/NDZ/2022/160 dated 21/03/2022				
6	Fir	e safety directives letter no.	N/A				
7		te of inspection	16/12/2024				
8		me of the inspecting officers	Yashwant Singh Meena, A.D.O / Laxmi Nagar				
9	Na	me of the designation of icer from the building side	Mr. Sanjay Vij (Owner)				
10		ar of construction	2006		ST PAGE		
11	Applicant's letter no. MHA Application No. 2024120917807 of 09/12/2024						
S.No	p	Minimum standard of fire revention and fire safety U/R	Requirement existing fire safety arrangements	Provided at site	Remarks MR/NMR		
1	Ac	cess to Building:			27/4		
	A	Road width	N/A	N/A	N/A N/A		
	В	Gate width	N/A	N/A	N/A		
	C	Width of internal road	N/A	N/A	IV/A		
2	Number, Width, Type and Arrangement of Exits:						
-	A	Number of staircases		01 no.	MR		
	light.	a Upper floor	01 no		N/A		
	-	c Basement	N/A	N/A	IVA		
	B	Width of staircases	0.00	15	MR		
		a Upper floor	0.80 mtrs.	1.5 mtrs	A. A.		
		b Basement	N/A	N/A	N/A		
	C	Protection of exits			STA		
		a Fire check door	N/A	N/A	N/A		
		b Pressurization	N/A	N/A	N/A N/A		
	D	No. of continuous staircases to terrace	N/A	N/A	IN/A		
	E	Width of corridor	N/A	N/A	N/A		
	F	Door size	1.0 mtr	1.0 mtr	MR		
3	Compartmentation:		2.0 21114		Mayor		
<i>-</i>	A	Fire check door	N/A	N/A	N/A		
	B	Sealing of electrical shafts	N/A	N/A	N/A		
	C	Fire rating of shaft door	N/A	N/A	N/A		
	D	Water curtain	N/A	N/A	N/A		
	E	Fire dampers	N/A	N/A	N/A		
	Smoke Management System:						
4	10000	Basement	N/A	N/A	N/A		
4	A	Basement	1 1/4 1	T. 11.1.7	14/17		

Toronto Guest House, 10072 to 10076, Gali No.1, Multani Dhanda, Phar Ganj, New Delhi.

-		Extinguisher:	10 Nos.	10 nos.	MR		
A	_	Total numbers	- Charle Sandardo		MR		
E		Гуреѕ	CO ₂ & ABC	CO ₂ & ABC	MR ·		
(ISI marking	ISI Marked	Provided	IVIX		
I	First-Aid-Hose Reel:						
1		Total numbers of each floors	01 no.	01 no.	MR		
-		Length of hose reel hose	30 mtrs	30 mtrs	MR		
-	_	Nozzle diameter	05 mm	05 mm	MR		
-	C	omatic Fire Detection and	Alarming System				
			Required	Provided	MR		
	A	Type of detectors	Required	Provided	MR		
	В	Location of main panel	N/A	N/A	N/A		
	C	Location of repeater panel	Required	Provided	MR		
	D	Alternate source of power	Required	Provided	MR		
	E	Hooters		Provided	MR		
8		EFA:	Required	Provided	MR		
9	Pul	blic Address System:	Required	Tioridod	71365		
10	Au	tomatic Sprinkler System:		N/A	N/A		
	A	Basement	N/A	The Water	N/A		
	В	Upper floor	N/A	N/A	N/A		
	C	Sprinkler above false ceiling	N/A	N/A	14/21		
11	Int	ternal Hydrants:		17/1	N/A		
11	_	Size of riser/down-comer	N/A	N/A	N/A		
	B	Number of hydrants per	N/A	N/A	N/A		
	-	Branch Hose box	N/A	N/A	IVA		
	-				NI/A		
12	_	ard Hydrants: Total number of hydrants	N/A	N/A	N/A		
	A		N/A	N/A	N/A		
	В	Hose box					
13		imping Arrangements:			1		
1		Ground level	N/A	N/A	N/A		
	A		N/A	N/A	N/A		
	В		N/A	N/A	N/A		
		Number of main pumps	N/A	N/A	N/A		
	D		N/A	N/A	N/A		
	E	Jockey pump head	N/A	N/A	N/A		
	F	Standby pump out put	N/A	N/A	N/A		
	G	Standby pump head	N/A	N/A	N/A		
	H		IVA				
_		stopping					
2	T	Terrace Level 450 LPM 450 LPM MR					
	A	Discharge of pump	450 LPM	30 mtrs	MR		
	В		30 mtrs	Provided	MR		
	C	Power supply	Required	Provided			
1	D	Auto starting of pump	Required	riovided	MR		





115 11 N/23

Toronto Guest House, 10072 to 10076, Gali No.1, Multani Dhanda, Phar Ganj, New Delhi.

14	Ca	Captive Water Storage for Fire Fighting:					
	A	Underground tank capacity	N/A	N/A	N/A		
	В	Draw-off connection	N/A	N/A	N/A		
	C	Fire service inlet	N/A	N/A	N/A		
1	D	Access to tank	N/A	N/A	, N/A		
	E	Overhead tank capacity	5,000 liters	5,000 liters	MR		
15	Exit Signage:		Required	Provided	△ MR		
16	Provision of Lifts:						
	A	Pressurization of lift shaft	N/A	N/A	N/A		
	В	Pressurization of lift lobby	N/A	N/A	N/A		
	C	Communication in lift car	N/A	N/A	N/A		
	D	Firemen's grounding switch	N/A	N/A	N/A		
	E	Lift signage	N/A	N/A	N/A		
17		andby Power Supply:	Required	Provided	MR		
18	Refuge Area:						
	A	Total area	N/A	N/A	N/A		
	В	Location	N/A	N/A	N/A		
19	Fire Control Room:						
	A	Detector system panel	N/A	N/A	N/A		
	В	Flow switch panel	N/A	N/A	N/A		
	C	PA system panel	N/A	N/A	N/A		
	D	Battery backup	N/A	N/A	N/A		
	E	Building floor plans	N/A	N/A	N/A		
20	Sp	ecial Fire Protection systems for	r protection of spe	cial Risks, if	N/A		

The fire protection system was randomly checked and tested and was found functional at the time of inspection. The earlier shortcomings issued vide letter no. F6/DFS/MS/GH/NDZ/2024/707 dated 03/11/2024 by this department hat been rectified by the management.

Keeping In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules of Directorate of Education the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2022/160 dated 21/03/2022, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended to be renewed.

No file is pending with me before disposal of this case.

Signature of the Inspecting Officer

Name : Yaswant Singh Meena

Designation: ADO /Laxmi Nagar

DO/CD

19/12/24

Dice (2003)

19/12/21

Denethy golloh

Aget N. D.T.O