

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI-110001

No.F6/DFS/MS/School/SZ/2021/ 109

Dated: 01/03/2021

To,

The Principal,
Sarvodaya Bal Vidyalaya,
Deendarpur (Jhatikra Mor) Delhi-110043.

Subject:-Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Sarvodaya Bal Vidyalaya, Deendarpur (Jhatikra Mor) Delhi-110043.


Sir,

This is in reference to your letter No-54(SPS School) PWD Edu. Sub-Divn M1-1 (N)/2020-21/49 dated-10/12/2020 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above-mentioned school from fire safety point of view in presence of Mr. K.D Mishra (Teacher) on 04/02/2021. During the course of inspection, the following points / shortcomings were noticed in the school building comprised of ground plus three upper floors.

1. First aid hose reel provided but not functional.
2. Down comer system provided but not functional.
3. A fire pump having 450 LPM provided but not functional.
4. Over Head water storage tank 5,000 liters capacity provided in place of 10,000 liters required.
5. Exit signage's are not provided.

In view of above, the school building can not be considered for grant of fire safety certificate at this stage. Therefore you are requested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully



(Atul Garg)
Director

Delhi Fire Services



Copy to:-1.The Executive Engineer (E) Division M1,ITI Campus Pusa New Delhi
2. M/s Arihant Builders T-96,Om Vihar, Uttam Nagar,New Delhi-110059.