

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F6/DFS/MS/School/2021/ 119

Dated: 02/03/2021

To

The Principal,  
Convent of Jesus and Merry School,  
01, Bangla Sahib Road, New Delhi.

**Sub: Regarding issuance /Renewal of FSC in r/o Covent of Jesus and Merry school  
Situatd at 01 Bangla Sahib Road, New Delhi.**

Sir,

This has reference to your E mail < cjm.delhi@yahoo.com> dated 17.02.2021 on the subject cited above. In this regard, it is to inform you that the site was inspected by officers concerned of this department on 22.2.2021 in the presence of Ms Arti and the following shortcomings were observed.

**1. Sr. Secondary school block ( Gr+ first floor )**

- a. Fire extinguishers are not provided as per IS 2190.
- b. Exit signages found inadequate.

**2. Middle School block ( B+ G + 2 upper floor )**

- a. Alternate staircase of .75 m is not provided in the basement.
- b. Fire check door is not provided in the basement.
- c. Fire extinguishers are not provided as per IS 2190.
- d. Hose reel is not covering entire area of block, require to be extended in left out area.
- e. Exit signages found inadequate

**3. Auditorium Block ( Basement + Gr. + 03 upper floors )**

- a. Fire check doors are not provided in the basement.
- b. MOEFA found non functional.
- c. PA system found non functional.
- d. Exit signages found inadequate
- e. Overhead tank capacity is provided 15,000 liter against the requirements of 20,000 liter.

In view of above shortcomings, fire safety certificate ( FSC) cannot be renewed/issued at this stage.

Yours faithfully



(Dr. S. K. Tomar)  
Dy. Chief Fire Officer  
Delhi Fire Service

**Copy to:-**

The Director of Education,  
Govt. of NCT of Delhi , Old Sectt.