

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI -110001

No.F6/DFS/MS/NDZ/2021/ 133

Dated:- 10.03.2021

To

The Principal,
Sarvodaya Kanya Vidyalaya,
Gazipur, Delhi-110096.
School ID-1002184.


Sub:- Regarding renewal of FSC in r/o Sarvodaya Kanya Vidyalaya, Gazipur, Delhi-96.

Sir,

This has reference to your letter No. SKV/GZP/2021/456 dated 20/01/2021 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 02/03/2021 in the presence of Mr. Arun Kr. Sharma (Estate Manager) and no progress was found observed against the shortcomings already communicated by this department vide letter No. F6/DFS/MS/school/2017/1056 dated 25/04/2017 (copy enclosed).

Hence, the Fire Safety Certificate cannot be considered at this stage.

Yours faithfully



(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No. *FB/DFJ/MS/School/2017/1056*

Dated: *25/04/17*

To,

The Principal,
Sarvodaya Kanya Vidyalaya,
Gazipur, Delhi-96.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Sarvodaya Kanya Vidyalaya, Gazipur, Delhi-96.

Madam,

Please refer to your letter SKV/GH/2017 dt-17/02/17 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school in the presence of principal to verify the fire safety arrangements in accordance with the Delhi Fire Service Act 2007 and Rules 2010. During course of inspection it was observed that the school building is comprised of ground plus three upper floors. Following shortcomings were observed:-

1. Only two Fire Extinguishers provided in place of twenty seven.
2. First Aid Hose reels provided but not functional.
3. Fire pump having 450 LPM out put at 40 m head provided but not functional and pump not on auto mode.
4. Over head water tank capacity of 5000 liters provided in place of 10,000 liters.
5. Exit signage not provided.

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully

W 25/4
(Vipin Kental)
Chief Fire Officer

ofe

1/5

Copy to:-

- 1 The Director of Education,
Government of N.C.T.Delhi.
Old Sectt, Delhi-54.
2. The Principal,
Govt.Sarvodaya Bal Vidyalaya,
Laxmi Nagar, Delhi-92

1/5
118-205
Delhi-96