

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/School/NDZ/2021/ 145

Dated: 12/03/2021

To
The Principal,
North DMC Primary Co-Ed School,
Gali Farhatullah, Kucha Pandit, (City Zone),
Delhi

Sub: - Regarding issuance of "Fire Safety Certificate" in r/o North DMC Primary Co-Ed School, Gali Farhatullah, Kucha Pandit, (City Zone), Delhi.

Madam,

With reference to Email dated 26.02.2021 on the subject cited above. It is to inform you that the School building has been inspected by the Assistant Divisional Officer (SPM) from this department on 09.03.2021 in the presence of Mrs. Anjum Begum (Incharge), and it was observed that the shortcomings already communicated by this department vide letter no. F6/DFS/MS/School/2013/975 dated 14.03.2013 (photocopy enclosed) has not been rectified till date except shortcoming mentioned at Sr. no. c. The school management is requested to rectify the shortcomings mentioned at Sr, no. a & b of the above referred letter at the earliest.

In view of above, Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,



(Dr. S.K. Tomar)

Dy. Chief Fire Officer

Tel: 011-23412025

etc [Signature]

Copy to:-

The Director of Education,
North Delhi Municipal Corporation, City S.P. Zone, Old Hindu College, Kashmiri Gate, Delhi

C-4

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001

NO: F6/DFS/MS/School/2013/975 Dated: - 14/05/13

To,

The Principal,
M.C. Primary School,
Kucha Pandit (City Zone)
Delhi:- 110006

Sub: - Inspection report in r/o M.C. Primary School, Kucha Pandit (City Zone), Delhi from fire safety & means of escape point of view.

Sir,

With reference to your letter No nil dated 20/09/2012 on the above cited subject, this is to inform you that the aforesaid school building have been inspected by the officer concerned of this department in presence of Mirza Furqan Ali, Principal of the School, on 05/03/2013 to verify the fire safety arrangements as per the directives of Education Department vide Circular No. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01-03-2011.

During inspection, it was observed that the said school building is comprised of ground + first floor. One staircase of width 0.93 mts found provided in the building. 01 Fire extinguisher of ABC type, electric bell and sand buckets found provided in the building. The following shortcomings were observed:-

- a. School Building is not approachable to the fire engines.
- b. One additional staircase of minimum 0.75 mts width is required.
- c. One ABC type fire extinguisher is required in first floor.

In view of the above shortcomings, 'Fire Safety Certificate' cannot be considered at this stage. You are requested to rectify the shortcomings under intimation to this department.

Yours faithfully


Chief Fire Officer
Delhi Fire Service


28/5/13

Copy to:-

The Director of Education,
MCD (North), Kashmere Gate, Nigam Bhawan, Delhi.