

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No. F6/DFS/MS/Hospital/2021/

24

Dated:- 06 /01/2021

To

Dr. Harvinder Singh Kukreja,
Kukreja Hospital,
D-36, Acharya Niketan, Mayur Vihar Phase-1,
Delhi-110091.

Sub: Regarding issuance of FSC in r/o Kukreja Hospital D-36, Acharya Niketan, Mayur Vihar Phase-1 Delhi-110091.

Sir,

This has reference to your letter no. nil dated 02/11/2020 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 05/12/2020 in the presence of Dr. Harvinder Singh Kukreja & Dr. Rumeet Singh Kukreja and the following shortcomings were observed:-

1. 02 staircase width of 1.20 & 1.30 meter provided instead of 2.0 & 1.5 meter required.
2. Smoke ventilation system not provided.
3. First-Aid Hose Reel is not provided.
4. MOEFA not provided.
5. Sprinkler system not provided.
6. Wet riser not provided.
7. One electrical and one diesel Pump of capacity 1620 LPM diesel and one electrical pump of capacity 180 LPM not provided.
8. Underground water tank capacity of 50,000 liter is not provided.
9. As built drawings with existing fire safety arrangements through building sanction authority through **online portal of MCD**.

Hence, Fire Safety Certificate can not be considered at this stage.

Yours faithfully

(Atul Garg)

Director

Delhi Fire Service

Copy to:-

The Director,
Directorate of Family Welfare,
Govt. of NCT Delhi,
B & C Wing, 7th floor, Vikas Bhawan, New Delhi.

ok
m