

C-50

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/2021/ 180

Dated: 5/4/21

To

The Manager,
Sun Smile Public School, (ID-1412137)
A-1/155, Aman Vihar,
Delhi-110086.

Subject: Issuance of Fire Safety Certificate in r/o Sun Smile Public School, (ID-1412137), located at A-1/155, Aman Vihar, Delhi-110086.

Sir,

Kindly reference to online mail dated 15.02.2021, received in this department on the subject cited above. In this connection it is to inform you that the premises of your school has been visited by the officer concerned of this department in presence of Sh. R.B Sharma, Manager on 18.03.2021 and observed that shortcomings already issued by this department letter of even No. 593 dated 26.08.2020 (Copy enclosed) are not yet complied. Therefore, you are advised comply all the shortcomings issued vide this department letter dated 26.08.2020 for further consideration in this matter.

Yours Faithfully

(Dhrampal Bhardwaj)
Dy.Chief Fire Officer
Tel;-01123412050

11/4/2021
D/C
D/C

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/2020/School/593

Dated: 26/08/2020

To

The Manager,
Sun Smile Public School, (ID-1412137)
A-1/155, Aman Vihar, Delhi-110086.

Subject: Issuance of Fire Safety Certificate in r/o Sun Smile Public School, (ID-1412137), located at A-1/155, Aman Vihar, Delhi-110086.

Sir,


This is in reference with your letter No.SSPS/30/2020 dated: 18.05.2020, received in outdoor diary no. O.D No.5300 dated 18.05.2020, on the subject cited above. The premise was inspected by the concern nominated authority of this department in presence of Smt. Murti devi on 08.08.2020 to verify the compliance of fire prevention and fire safety measures required under the rules. The issue of FSC is rejected under sub rule (4) of Rules 35, in the view of reasons mentioned below:

1. An overhead water storage tank capacity of 1000 ltr is provided against the required of 2500 ltr
2. The required exit signage are not provided.
3. Pump found not functional.
4. Hose reel found not functional.
5. Channel gate are provided at final exit & each corridor.

In this regard as stipulated in sub Rule (1) of Rule 37 of DFS Act-2007 & Rules 2010 you are advised to apply again in Form "J" along with a declaration from owner/occupier on Form "K" as required under Rule 38 that all the fire prevention and fire safety measures provided in the building/premise are in best repairs. The web links for DFS Act-2007/ Rules 2010 & Form "J" & "K" are as under:

http://www.delhi.gov.in/wps/wcm/connect/doi_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/
http://www.delhi.gov.in/wps/wcm/connect/doi_fire/FIRE/Home/Forms

Yours Faithfully


(Dhrampal Bhardwaj)
Dy.Chief Fire Officer
Tel:-01125156707