

c/22

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No. F6/DFS/MS/School/2021/ 216

Dated 16/04/2021

To,

The Manager,
David Model Sr. Sec. School,
Main Road Tukmirpur,
Delhi-110094

Sub:- Regarding Issuance Fire Safety Certificate in r/o David Model Sr. Sec. School located at Main Road Tukmirpur, Delhi-110094.

Sir,

With reference to your letter No. nil dated 15/01/2021 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view on dated 03/02/2021 in presence of Mr. Rambir Singh, Manager of the School. The following points / shortcomings were noticed in the building comprised of ground plus three upper floors (two separate blocks).

1. Only 10 fire extinguishers provided in place of 18 fire extinguishers as required.
2. First-Aid hose reels (01 nos.) not functional at each floor and each block at the time of inspection.
3. A fire pump having 450 LPM output at 40 meters head not functional in each block.
4. Over head tank 2,000 liter (Old block) & 5000 liter (new block) provided in place of 10,000 liter in each block as required.
5. Exit signage not provided in each block.

In view of above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully


13/4/21

(Dr. S. K. Tomar)
Dy. Chief Fire Officer

o/c 

Copy to:-

The Dy. Director of Education,
B-Block, Yamuna Vihar
Delhi 110053