

c/20

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE  
NEW DELHI- 110 001**

No. F6/DFS/MS/School/2021/NDZ/ 214

Dated: 16/04/2021

To,

The Principal  
Govt. Sarvodaya Kanya Vidyalaya,  
E-Block, Nand Nagri,  
Delhi-110093

Sub:- Regarding issuance of Fire Safety Certificate in r/o Govt. Sarvodaya Bal Vidyalaya, E-Block, Nand Nagri, Delhi.

Sir,

Please refer to your Email SKV/1106113 dated 21/01/2021 on the subject cited above. In this regard, it is to inform you that the inspection of the above said premises was carried out by the officer concerned of this department in presence of Mrs. Alka Choudhary, Principal of the school on dated 03/02/2021. During the course of inspection, the following shortcomings:-

1. First Aid Hose reels provided but not functional.
2. Fire pump having 450 LPM output at 40m head provided but not functional.

In view of above, the building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully

  
13/4/21

(Dr. S. K. Tomar)  
Dy. Chief Fire Officer



Copy to:-

1. The Director of Education,  
B-Block, Yamuna Vihar,  
North - East, Delhi-110053.