GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE **NEW DELHI- 110 001**

No. F6/DFS/MS/School/2021/NDZ/ 308

Dated 24 06 2021

To.

The Principal, EDMC Primary School. Karawal Nagar, Delhi 110094

Sub:- Regarding Issuance Fire Safety Certificate in r/o E.D.M.C Primary school at Karawal Nagar, Delhi 110094.

Sir.

With reference to your email Latter No.nill dated 19/03/2021 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned School from fire safety point of view in presence of Mr. Ashok (Teacher) of the School. During the course of inspection it was observed that the following points / shortcomings were noticed in the building comprised of ground plus two upper floors.

- 1. The Width of the staircase 1.50 meters wide are not provided
- 2. First-Aid hose reels 01 Number provided in place of 02 number as required.
- 3. A terrace pump having 450 LPM output at 40 meters head not functional
- 4. Exit Signage are not provided.

In view of above, the building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully

Director

Copy to:-

The Director of Education, EDMC Udyog Sadan, Plot No. 419, FIE, Patpargani, Delhi 92