## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/School/2021/NDZ/329

Dated: 05/07/2021

To,

The Principal, EDMC Primary School, Saraswati Bhandar, Gandhi Nagar, Delhi-110031

Subject:- Regarding to issue Fire Safety Certificate.

Sir,

With reference to email ID hos1051128@gmail.com dated 20/03/2021 on the subject cited above, it is informed that officer concerned of this department inspected the school building on 23/06/2021, it was noted that the shortcomings issued vide letter No. F6/DFS/MS/School/2012/4460 dated 03/12/2012 and No. F6/DFS/MS/School/2018/NDZ/4264 dated 10/10/2018 have not been complied as yet (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours Faithfully,

(Dr. S. K. Tomar) Dy. Chief Fire Officer

Copy to:-

The Director of Education, EDMC, Udyog Sadan, Plot no. 419, FIE, Patparganj Industrial Area, Delhi-110092

C-9

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/School/2018/NDZ

14264

Dated: | 0 | 1 0 | 1 8

To,

The Principal, M/s EDMC Primary School, Subhash Mohalla, Gandhi Nagar, Delhi- 31.

**Sub:** - Regarding issuance of Fire Safety Certificate in r/o EDMC Primary School at Subhash Mohalla, Gandhi Nagar, Delhi- 31.

Madam,

Please refer your letter no. Nil dated 24.08.2018, on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has been carried out inspection in presence of Smt. Reeta Rani, Principal of the school. During the Inspection it was observed that the shortcomings as communicated earlier vide letter no. F6/DFS/MS/School/2012/4460 dated 03/12/12 are yet to be rectified. Copy of the same is enclosed for your ready reference.

Yours faithfully

(Vipin Kental) Chief Fire Officer Delhi Fire Service

ole

OB

Copy to:-

The Directorate of Education, EDMC, Udyog Sadan, Plot no. 419, FIE, Patparganj Industrial Area, Delhi- 110092.

CH

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/ms/school/2012/4460

Dated: 03 112 /12

To.

The Principal,

M.C. Primary Co-ed School,

Saraswati Bhandar, Gandhi Nagar,

Delhi-31.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o M.C. Primary Co-ed School, Saraswati Bhandar, Gandhi Nagar, Delhi-31.

Madam,

Please refer to your letter on the subject cited above, In this connection this is to inform you that officer concerned of this department inspected the school to verify the fire safety arrangements as per circular issued by Director of Education dated 01.03.2011. At the time of inspection Mrs. Rita Rani, Incharge was present and observed that the school building is comprised of ground plus one upper floor only. During the course of inspection, it was also noticed that-

- 1. The Premises is not accessible to fire engines.
- 2. An additional staircase is required.
- 3. One CO<sub>2</sub> type 2.5 kg capacity or one ABC type fire extinguisher with ISI mark were not found provided for every 300 square meters of covered area or part there of each floor level.

Due to which the building cannot be considered for issuance of Fire Safety Certificate.

Yours faithfully

(DR. T.S. SHARMA)

Dy. Chief Fire Officer (NDZ)

Delhi Fire Service

Copy to: -.

The Director of Education.

East Delhi Municipal Corporation,

419, Udyog Sadan, Patparganj Industrial Area, Delhi-92.