

G-18

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW
DELHI – 110001

No. F6/DFS/MS/School/WZ/2021/340

Dated: 12/07/2021

To,

The Principal,
Darbari Lal DAV Model School,
BN Block, Shalimar Bagh,
Delhi-110088.

Sub. :-Renewal of Fire Safety Certificate in r/o Darbari Lal DAV Model School, BN Block, Shalimar Bagh, Delhi-110088.

Sir,


Please refer to your email dated 24.6.2021 on the subject cited above. In this connection it is to inform you that the said School building have been inspected by the officer concerned of this department on 02.7.2021 in presence of Sh. Anand (Supervisor) & Sh. Rajesh (Assistant) to check workability/functionability of Fire safety systems provided in the building.

During inspection, the following shortcomings have been observed:-

1. One of Staircases in Block No. 1 is closed with brick wall at 3rd floor.
2. Exhaust fan in basement are provided but found non-functional.
3. Portable Fire Extinguishers are provided but not refilled/updated.
4. First Aid Hose reels are provided but non functional due to leakage in pipe at some floors.
5. Some speakers of PA system are non functional.
6. Terraces tanks for firefighting found empty (bore well is under repair).
7. Exit signs not displayed at some prominent places.

In view of the above shortcoming, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Education Authority may take suitable necessary action as deemed fit.

Yours faithfully,


(Dharampal Bhardwaj)
Dy. Chief Fire Officer
(West Zone)

Copy to:-

1. The Director, Directorate of Education Old Secretariat Delhi – 110054.
2. Sh. Joginder Kumar Lamba, Gerrage No. 35, First Floor, Near Durga Mandir, Gulabi Bagh, New Delhi-110007. In reference to his complained through PGMS dated 03.05.2021