

C/34

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No.F6/DFS/MS/School/2021/MN/339

Dated: 12/07/2021

To

The Principal,
S.S.D. Saraswati Bal Mandir Sr. Sec. School
Road no. 70, West Punjabi Bagh, New Delhi

**Sub: - Inspection report in respect of S.S.D. Saraswati Bal Mandir Sr. Sec.
School Road no. 70, West Punjabi Bagh, New Delhi -110026**


Sir,

This is in reference to the dated 08/06/2021, regarding renewal of Fire Safety Certificate in respect of aforesaid School. In this connection, it is to inform you that the premises was inspected by officer concerned of this department on 29/06/2021 in the presence of Smt. Reena Verma (Principal) to check the fire safety arrangements. During inspection, it was observed that the said Building is comprised of Ground Plus three upper Floors. Fire safety arrangements such as Fire Extinguishers, Hose reels, Sprinkler system etc. are provided. However, following shortcomings were observed: -


1. First Aid Hose reels are provided but not working.
2. Sprinkler System provided in Basement but not working.
3. Terrace fire pump of 450lpm & at Ground Level fire pump of 900 LPM is provided but not working.(In previous FSC it is allowed 900 LPM at Ground Floor & 450 LPM at terrace floor).
4. Overhead water storage tank of capacity 15,000 ltrs is removed.

In view of above shortcomings, the application for Renewal Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The licensing Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully


(Dharampal Bhardwaj)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:- The Directorate of Education Old Secretariat Delhi - 110054

o/c

09/07/2021