

C 16

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE  
NEW DELHI- 110 001**

No. F6/DFS/MS/School/2021/NDZ/ 367

Dated: 26/07/2021

To,

The Principal  
Sarvodaya Kanya Vidyalaya,  
C- Block, Dilshad Garden  
Delhi-110095

Sub:- Regarding issuance of Fire Safety Certificate in r/o Sarvodaya Kanya Vidyalaya, C-Block, Dilshad Garden, Delhi 110095.


Sir,

With reference to your email letter No. nil dated 22/03/2021 on the subject cited above. In this regard, it is to inform you that the inspection of the above said premises was carried out by the officer concerned of this department in presence of Mrs. Freda J. Baxla, Head of the school. During the course of inspection the following points / shortcomings were noticed in the school building comprised of ground plus three upper floors (New building blocks).

1. First Aid Hose reels provided but not functional.
2. Terrace pump having 450 LPM output at 40m head provided but not functional.

In view of above, the building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully

  
(Dr. S. K. Tomar)  
Dy. Chief Fire Officer



Copy to:-

1. The Director of Education,  
B-Block, Yamuna Vihar,  
North - East, Delhi-110053.