Dated: 27/07/2021

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110001

No.F6/DFS/MS/School/2021/SZ/ 370

To,

The Principal, Govt. Sarvodaya Kanya Vidyalaya, Hastsal, New Delhi-110059.

Sub: - Regarding grant of NOC from fire safety point of view in r/o Govt. Sarvodaya Kanya Vidyalaya, Hastsal, New Delhi-110059.

Sir,

Please refer to your letter no. Nil Dated -05/07/2021 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department have carried out the inspection of the above-mentioned school building from fire safety point of view. During the course of inspection, the following points / shortcomings were noticed:

1. First aid hose reel provided but not functional in new block.

2. Down comer system provided but not functional in new block.

3. Fire Pump provided but not functional & auto mode in new block.

4. Exits signage's are not provided in new block.

In view of above, the school building cannot be considered for grant of fire safety certificate at this stage .Therefore you are suggested to rectify the above said shortcomings under the intimation to this department for further course of action.

Yours faithfully

(Sunil Chawdhary) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

 Director of Education, GNCT of NCT of Delhi, Old Secretariat, Delhi-110054.