

C-28

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI -110001**

No.F6/DFS/MS/NDZ/2021/ 410

Dated:- 12/08/2021

To

The Principal,  
Govt. Girls/Boys Sec. School,  
Kondli Gharoli, Mayur Vihar-III,  
Delhi-110096.

**Sub: Regarding grant of FSC in r/o Govt. Girls/Boys Sec. School at Kondli Gharoli, Mayur Vihar-III, Delhi-110096 (School I.D- 1002352).**

Sir,

This has reference to your email dated 26/07/2021 on the subject cited above. In this regard, it is to inform you that the site was re-inspected by the officer concerned of this department on 30/07/2021 in the presence of Mr. Prabhansh(Supervisor) and observed that the site is under construction (photo enclosed). Hence, inspection could not be completed.

Further school authority is requested to submit approved/as built plan through building sanctioning authority/local authority, so that case can be considered accordingly.

Hence, the Fire Safety Certificate cannot be considered at this stage.

Yours faithfully

  
(Atul Garg)  
Director

Delhi Fire Service

ok  
m

Encl: as above