

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No. F.6/DFS/MS/School/2021/NDZ/ 428

Dated:- 25/08/2021

To,

The Principal,
EDMC Nigam Pratibha Vidyalaya,
Nand Nagri C-II, Shahdara,
Delhi-110093


Subject:- Regarding Fire NOC for EDMC Primary School, Nand Nagri C-II.

Sir,

With reference to email ID edmcnnc2@gmail.com dated 28/07/2021 on the subject cited above, it is informed that officer concerned of this department inspected the school from fire safety point of view in presence Sh. Mohan Singh, Incharge on dated 11/08/2021, it was noted that the shortcomings issued vide letter No. F6/DFS/MS/School/2019/6823 dated 15/11/19 have not been complied as yet & also firefighting system which has been provided in the school building, was not functional at the time of inspection (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours Faithfully,



(Dr. S. K. Tomar)
Dy. Chief Fire Officer

Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No.419, FIE,
Patparganj, Delhi-92

C/13

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI-110001

No.F6/DFS/MS/School/2019/ 6823

Dated: 15/11/19

To,

The Principal,
M/S EDMC Pratibha Vidyalaya
Nand Nagri C-II, Shahdara,
Delhi-110093

Subject: -Regarding grant of Fire Safety Certificate in r/o M/S EDMC Pratibha School
Nand Nagri C-II, Shahdara, Delhi-110093.

Sir,

With reference to your letter No. nil dated 07/09/2019 on the subject cited above, it is informed that officer concerned of this department carried out inspection of the school from fire safety point of view in presence of Principal of the school. During the course of inspection, it was observed that the building comprised of ground plus three upper floors and are provided with fire extinguishers and first aid hose reels which were functional at the time of inspection. Discharge capacity and head of the Fire Pump was not ascertained in absence of technician/documents, so you are requested to supply following information at the earliest:

1. Discharge capacity and Head of the fire pump mounted at terrace for feeding hose reels.

Yours faithfully


(Sunil Chawdhary)
Dy. Chief Fire Officer

Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj, Delhi 92

