

c-33

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

NO. F-6/DFS/HQ/ 2021/ 21

Dated 31 / 8 /2021

To,

The Ramjas College,  
North Campus, University of Delhi,  
Delhi-110007.

Sub: - Regarding joint inspection carried out for completion certificate in r/o Ramjas College, North Campus, University of Delhi, Delhi-110007.

Sir,

Please refer completion case I.D No-10089927 Dated 24.08.2021 on the subject cited above. In this connection this is to inform you the above mentioned site was visited by the officer concerned of this department on 24.08.2021 to verify the fire safety arrangements installed in the building as per issued fire safety recommendations vide letter of even no 256 dated 14.10.2016. At the time of inspection Sh. Sanjay Sharma (Executive. Engg.) MCD, Sh. Kuldeep Singh (AE, MCD), Sh. Partap Singh (Architect) & Sh. Hari Mohan from college side was also present at site. During the course of the inspection it is observed that the building is comprised of ground + five upper floors. The following observations are made:-

- 1 06m internal road for fire tender movement is not provided.
- 2 Electrical shafts are not sealed.
- 3 Fire extinguisher not provided at site.
- 4 Fire hydrant riser shaft is not sealed at each floor.
- 5 Hose reel hose provided but not functional and nozzle are not provided.
- 6 MOEFA systems not provided in the building.
- 7 P.A systems is not provided.
- 8 Internal hydrant provided but not functional and hose boxes not provided at all upper floors.
- 9 Terrace level firefighting pump capacity of 900lpm provided but not connected with panel.
- 10 Terrace level fire water tank provided with domestic use and inspection ladder is not provided.
- 11 Exit signage's floor level signage and lift signage's are not provided anywhere in the building.
- 12 There are four lifts provided in the building without lift shaft and lobby's are not pressurized.
- 13 Fire check doors not fitted as per norms.
- 14 As per sanctioned drawing fire control room not provided at entrance of ground floor.
- 15 Expansion joints are not sealed properly at some places.

Keeping in view of above non-compliance of Fire Safety provisions, Fire Safety Certificate cannot be considered at this stage.

Yours faithfully

(Atul Garg)  
Director

Ph: 011-23414000

Copy to:-

1. The Dy. Commissioner, (Civil Line Zone) North Delhi Municipal Corporation, 16, Rajpura Road, New Delhi-110054.