

G27

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No.F6/DFS/MS/School/2021/ 443

Dated 27/08/2021

To,

The Principal,
EDMC Primary School,
Chandu Park, Delhi-110051

Subject:- Request for issuing a Fire Safety Certificate.

Sir,

With reference to your e-mail ID edmcpschandupark2shift@gmail.com dated 16/08/2021 on the subject cited above, it is informed that officer concerned of this department inspected the school building from fire safety point of view in presence of Ms. Anjali Sharma, Principal of the school on dated 23/08/2021, it was noted that the shortcomings issued vide letter No. F6/DFS/MS/School/2020/782 dated 18/12/2020 have not been complied as yet (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours Faithfully,


27/8/21

(Dr. S. K. Tomar)
Dy. Chief Fire Officer



Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj Industrial Area, Delhi-92

C/24

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No.F6/DFS/MS/School/2020/ 782

Dated 18/12/2020

To,

The Principal,
EDMC Primary School,
Chandu Park, Delhi-110051

Sub:- Request for issuing a Fire Safety Certificate.

Sir,

With reference to your e-mail ID edmcpschandupark2shift@gmail.com dated 13/11/2020 on the subject cited above, it is informed that officer concerned of this department inspected the school from fire safety point of view in presence of Ms. Meena Kumari, Principal of the School on dated 09/12/2020. The School building comprises of ground plus two upper floors. During the course of inspection following observations were made:-

1. A fire pump with 450 liters per minute discharge at 40 meters head (4kgf/sq.cm.) is required to be provided at terrace level.
2. Firefighting system which has been provided in the building, was not functional at the time of inspection.

In view of the above, the school building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to provide the above mentioned fire safety arrangements under intimation to this office for further course of action.

Yours Faithfully,


18/12/20

(Dr. S. K. Tomar)
Dy. Chief Fire Officer



Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj Industrial Area, Delhi-92