

G-35

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE  
NEW DELHI- 110001

No. F6/DFS/MS/School/2021/SZ/ 436

Dated: 27/08/2021

To,

The Principal,  
Sarvodaya Kanya Vidyalaya,  
SPS Block, Matiala, New Delhi-110059.


**Sub:** - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Sarvodaya Kanya Vidyalaya, SPS Block, Matiala, New Delhi-110059.

Sir,

This has reference to your letter No. GSVV/Matiala/NOC dated 09/08/2021 on the subject captioned above. In this connection, it is to inform you that the premise was inspected on 09/08/2021 by the officer concerned of this department in the presence of Smt. Sharmila (HOS) verify the compliance of shortcomings already communicated by this department vide letter no.F6/DFS/MS/School/2020/SZ/654 dated 30/09/2020. During the course of inspection it was observed that the shortcomings have not been rectified.

In view of above, the fire safety certificate can not be considered at this stage. You are requested to rectify the shortcomings under intimation to this department for further course of action.

Yours faithfully



(Sunil Chawdhary)  
Dy. Chief Fire Officer



Copy to:-

1. The Director of Education,  
Govt. of NCT of Delhi, Old Secretariat,  
New Delhi-110054.

c-28

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2020/SZ/654

Dated: 30/09/2020

To,

The Principal,  
Sarvodaya Kanya Vidyalaya,  
SPS Block, Matiala, New Delhi-110059  
161807matiala@gmail.com

Sub: - Regarding renewal of Fire Safety Certificate in r/o Sarvodaya Kanya Vidyalaya, SPS Block, Matiala, New Delhi-110059.

Sir,

This has reference to your email letter dated 29.08.2020 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 16.09.2020 to see the compliance of the requisite fire safety measures. Sh. Dubey (Estate Manager) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of ground floor plus three upper floors was issued FSC by this department vide letter no. F6/DFS/MS/School/201/SZ/1484 dated 12.10.2017. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

1. Hose reel system provided but not functional.
2. Fire pumps having capacity 450 LPM provided but not functional on auto mode.
3. Overhead water storage tank of 10,000 ltrs. capacity provided but leak.
4. Exit signs are missing at few places.

You are advised to rectify the above-mentioned shortcomings and apply in Form "J" & "K" for taking further action as necessary for renewal of Fire Safety Certificate.

Yours Faithfully,

(S.S. TULI)

Dy. CHIEF FIRE OFFICER  
SOUTH ZONE

Copy to:-

Director of Education,  
Govt. of NCT of Delhi, Old Secretariat,  
New Delhi - 110054

(with a request to take further action as school does not have fire NOC)

28/9/20