GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No.

F.6/DFS/MS/School/SZ/2021/ 474

Dated: 07/09/2021

To

The Principal

Sarvodaya Kanya Vidyalaya,

Malviya Nagar, New Delhi- 110017.

Sub: Regarding issue of Fire Safety Certificate (FSC) in r/o Sarvodaya Kanya Vidyalaya, Malviya Nagar, New Delhi- 110017.

Sir,

This is in reference to your Gmail dated 18/08/2021 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on 28.08.2021 and observed that the shortcoming intimated vide letter no. F.6/DFS/MS/School2019/SZ/4994 dated 20/08/2019 has yet not been complied. (Copy Enclosed for ready reference).

In view of above, you are again requested to rectify the shortcoming under intimation to this department for further action.

Encl: As above

Yours faithfully,

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ) DELHI FIRE SERVICE

MIN

Copy To:-

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/School/2019/SZ/ 4984

Dated: 20/8 /2019

To

The HOS/Vice Principal, Sarvodaya Kanya Vidyalaya, Malviya Nagar, New Delhi–110017

Sub: Reg. issuance of Fire NOC in r/o SKV, Malviya Nagar (ID: 1923046).

Sir/Madam,

This is in reference to your letter No. SKV/MN/111 dated 16/04/2019 received in this department outdoor dairy No. 9453 dated 16/04/2019 on the subject cited above. In this connection, it is to inform you that school premise have been visited by officer concerned of this department on 03/08/2019 in the presence of Mr. R. Mathur (Estate Manager) to verify the compliance of fire prevention and fire safety measures required under the rules. During the inspection, it was observed that there are material changes in the building as additions/alterations have been made in the building/premises affecting the fire prevention and fire safety measures including the means of escape. Two additional building blocks of ground plus three upper floors (G+3) and ground plus two upper floors (G+2) have been constructed with in the school premises, both old and new blocks are interconnected. Previously, the school building comprised of ground plus two upper floors only was issued fire safety certificate by this department vide letter No. F.6/DFS/MS/SZ/School/2015/SZ/254 dated 24/02/2015. Thus to adjudge the applicability of fire prevention & fire safety measures, the following documents/information are required to be provided.

- 1. Sanctioned / Completion plan of the building.
- 2. As build plan of the building, if sanctioned/completion plan is not available.

In view of above, issuance of Fire Safety Certificate cannot be considered at this stage. You are requested to submit required documents/information for further action in this matter.

Yours faithfully,

Chief Fire Officer Ph: 011-23414250

Copy to: -

1. The Dy. Director of Education (South), Directorate of Education (District South), Govt. of NCT of Delhi, Sector–3, R.K. Puram, New Delhi–110022