

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No. F.6/DFS/MS/School/2021/SZ/ 30

Dated: 14.01.2021

To

The Principal,  
The Shri Ram School,  
D-3, Street Vasant Vihar,  
New Delhi 110057

Sub:- Renewal of Fire Safety Certificate in r/o The Shri Ram School, D-3, Street Vasant Vihar, New Delhi 110057.


Sir,

This has reference to your Gmail dated 12/12/2020 on the subject cited above. In this connection, the said school premises have been inspected by concerned nominated of this department on 24/12/2020 in the presence of Mr. Mahinder Singh (Admn.). During the inspection it was observed that school is comprised of two side, one side B+G+2 upper floors and other side G+3 upper floor interconnected block. The shortcomings observed are as below.

1. The management of school has constructed one temporary class room in the basement near staircase.
2. The management has erected iron structure and one temp office in between building and main gate, now the school building is not accessible to fire engine as there is an encroachment over internal road.
3. Terrace level pump capacity 450 LPM not working.
4. Overhead tank capacity 5000 ltrs used for domestic works.
5. Exit signage found removed.

In view of above shortcomings, renewal of Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcoming under intimation to this department for further action in the matter.

Yours faithfully,



(Sunil Chawdhary)  
Dy. Chief Fire Officer (SZ)  
Delhi Fire Service

Copy to: -

1. Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054