

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEWDELHI-110001

No. F.6/DFS/MS/SZ/2021/

1833

Dated :-

10/09/2021

To

The Estate Manager,
Padma Tower- II,
22, Rajendra Place, New Delhi-110008.

Subject: -Regarding renewal of Fire Safety Certificate in r/o Padma Tower- II located at 22, Rajendra Place, New Delhi- 08.

Sir,

Please refer to your letter Ref no. Nil dated 26.02.2021 on the subject cited above. In this connection it is to inform you that the above said business building have been inspected by the officer concerned of this department on 17.08.2021 in presence of Sh. Chandeshwer & Prem Kumar (Manager) to check the workability of fire safety systems provided in the building. The building is comprised of basement, Lower ground, upper ground plus eight upper floors.

During the inspection, following shortcomings have been observed:-

1. Fire check door in few places are found in damaged condition & door closer found removed.
2. MOEFA system found provided but not functional.
3. P.A system found provided but not functional.
4. Main electric pump found not functional on auto mode.
5. RRL hoses are in damaged condition kept in hose boxes.
6. Detection system found not functional.
7. 7th floor found closed.

In view of the above shortcomings fire safety cannot be renewed at this stage. You are advised to rectify the above mention shortcomings under intimation to this department for taking further necessary action.

Yours faithfully

(Ajul Garg)
Director

Delhi Fire Service

01/09/21