GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/2021/NDZ/ 1898

Dated: 1709/2021

To,

The Managing Director, Delhi Metro Rail Corporation, Metro Bhawan, B. K. Road, New Delhi.

Subject:- Property Development at 7th Floor IT Park Block-1, Shastri Park, New Delhi: Fire incident at CERT-In office on dated 20.07.2021.

Sir,

With reference to letter No. DMRC/CGM/PD/ITP-1/7F/MEITY/2021/230 dated 17/08/2021 on the subject cited above, it is informed that officers concerned of this department inspected the premises in presence of Mr. Amit on dated 03/09/2021, and observed that the shortcomings issued vide letter No F.6/DFS/MS/2021/1443 dated 26/07/2021 have not been complied as yet (The copy of the same is enclosed for your reference).

Therefore, you are requested to rectify the shortcomings communicated vide above mentioned letter under intimation to this office for further action.

Yours Faithfully Directo

Copy to:-

- The CEO, DDMA, 5 Shamnath Marg, Delhi-54
- 2. The Dy. Commissioner of Police, East District, New Delhi

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F. 6/DFS/MS/2021/ 1443

Dated. 26.07.2021

To,

The Managing Director, Delĥi Metro Rail Corporation Metro Bhawan, BK Road, New Delhi

Sub: Information regarding occurrence of fire at 7th floor, CERT-in office, Building Block-1, at IT Park, Shastri park, Delhi on 20.07.2021 at 2044 Hrs.

Sir,

This is to inform you that a fire incident occurred at above mentioned address was reported to DFS on 20.07.2021 at 2044 Hrs. The fire was extinguished after the tedious efforts of the firefighting team. During the fire fighting operation, it is observed that the automatic sprinkler/fire firefighting system and the smoke management system installed in the building did not work. The Fire Safety Certificate to the building was issued vide letter NO. F 6/DFS/MS/2019/1273 dated 14.06.2019. This indicates a serious flaw on the part of building management.

Keeping in view, the immense importance of the building and the safety of the occupants, the occurrence of such mishaps must be stopped, accordingly it is requested to ensure the following measures:

- 1. Each and every building in IT Park must have fire safety management plan in place and adequately practiced by each and every occupant.
- 2. Trained manpower shall be available to ensure compliance of all prevention and fire safety measures and effective operation thereof.
- 3. All the building blocks should be checked from fire safety point of view and ensure that the entire fire prevention & fire safety systems are in functional condition. Any shortcoming in the fire prevention and fire safety systems be got repaired at the earliest.
- 4. The intimation regarding occurrence of any fire must be given to fire control room without any delay, as in case of fire every second adds the destruction and make the fire fighting operation complex.
- 5. All electric cables ducts and shafts shall be properly sealed at all floors with fire resisting material of 02 hours rating in all the buildings so that the fire / smoke remains confined to the area where fire incidents has occurred and does not spread to the remaining part of the building.
- The Building should not used for any purpose till the clearance from fire safety point of view is obtained from this department.

The compliance report of the above be submitted in this department at your earliest.

Yours faithfully,

Director

T. No. 23414000

Copy for information to:-

- 1. The CEO, DDMA, 5 Shamnath Marg, Delhi-54
- 2. The Dy. Commissioner of Police, East District, New Delhi

Follow frequent hand sanitization, use face mask and maintain physical distancing to prevent the spread of Corona