

FO

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/School/2021/SZ/ 509
To

Dated: 22/09/2021

The Principal,
Holy Child Convent School,
Baisla Complex, G-320, Block,
M.B Extn, Badarpur, New Delhi 110044.

Sub: Regarding issue of Fire Safety Certificate (FSC) in r/o Holy Child Convent School,
Baisla Complex, G-320, Block, M. B Extn. Badarpur New Delhi 110044.

Sir,

This is in reference to Gmail dated 27/08/2021 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on 10/09/2021 and observed that the shortcoming intimated vide letters of even no 6445 dated 28/10/2019 has yet not been complied. (Copy Enclosed for ready reference).

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

Encl: As above



(SUNIL CHAUDHARY)
DY. CHIEF FIRE OFFICER (SZ)

Copy to:-

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi 110054

c7

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/School/2019/SZ/ 6445

Dated: 28/10/19

To

The Manager,
Holy Child Convent School,
Baisla Complex, G-320, Block,
M.B. Extn., Badarpur,
New Delhi-110044

Sub: Issuance of Fire Safety Certificate.

Sir,


This has reference to your letter no. Nil dated Nil on the subject cited above. In this connection the school premises was visited by the officer concerned of this department on 05/09/2019 and observed that the school building is comprised of ground plus three upper floors.

It is further to inform that to ascertain the applicability of fire prevention & fire safety measures, the following documents/information are required to be provided.

1. Sanctioned/Approved/Regularised/Completion Plans of school building. In the absence of these plans, as built plans duly signed by the owner/occupier and a registered architect.
2. Recognition certificate issued by D.O.E. to ascertain the date of commencement of school.

In view of above, issuance of Fire Safety Certificate cannot be considered at this stage. You are requested to submit required documents/information for further action in this matter.

Yours faithfully,



(Atul Garg)

Chief Fire Officer
Tel: 011-23414250

etc

Copy to: -

1. The Dy. Director of Education (South), Directorate of Education (District South), Govt. of NCT of Delhi, Sector-3, R.K. Puram, New Delhi-110022