

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F.6/DFS/MS/2021/NDZ/ 1957

Dated 24/9/2021

To,

The Executive Engineer,
CPWD, Safdarjung Hospital Electrical Division,
New Delhi – 110002.

**Sub:- Regarding renewal of FSC in r/o Manak Bhawan 9, Bahadur Shah Zafar Marg,
New Delhi – 110002.**

Sir,

This has reference to your letter No 19(1)/DB/SHED/2020-2021/1263 dated 24.08.2021 on the subject cited above, it is to inform that the site was inspected by the officers concerned of this department on 13/09/2021 in the presence of Sh. Vishal Tomar, Scientist E & Sh. Praveen , AE (E) CPWD Sh. Vinod and the following shortcomings were observed: -

1. Electric shaft/openings are not sealed properly.
2. Smoke management system in basement found nonfunctional.
3. Detectors provided but not functional at some location.
4. Electric fire Pump found nonfunctional.
5. Terrace fire pump found nonfunctional
6. Lift signages and exit signage found in-adequate.
7. Corridors found encroached with almerhas , records, waste furniture and same should be removed from the corridor.

In view of above shortcomings, request for renewal of fire NOC is rejected. The occupancy of building /premises, in absence requisite fire & life safety arrangements, shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully


(Atul Garg)
DIRECTOR
Delhi Fire Service

✓ Copy to

1. Sh A.K.Das , Head, PMWD, BIS Manak Bhawan , 09, Bahadur Shah Zafar Marg , New Delhi.