

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110001

No. F6/DFS/MS/School/2021/SZ/ 4)

Dated: 27/01/2021

To,

The Principal,
Maharishi Dayanand Public School,
J-3/206-207, Rajouri Garden, New Delhi-110027.

Sub: -Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Maharishi Dayanand Public School, J-3/206-207, Rajouri Garden, New Delhi-110027.

Sir,

Please refer to your letter 8/EDU/MDPS/Fire Dated 28/12/2020 on the subject cited above. In this connection it is to inform you that officer concerned of this department inspected the school to verify the fire safety arrangements in accordance with the NBC Part-IV. At the time of inspection Sh. Omprakash Arora (Chairman) was present and it was observed that the school building is comprised of ground plus two upper floors and have following shortcomings:-

1. An additional staircase having width of 1.5 m shall be required.
2. First Aid Hose reels not provided.
3. Fire pump having 450 LPM output at 40 m head not provided.
4. Over head tank capacity of 10,000 liters not provided
5. Exit signage's not provided.

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully,



(Atul Garg)
Director

Delhi Fire Service

Copy to:-

The Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
Delhi-110054.