GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE

No. F6/DFS/MS/SZ/2021/ 2009 To.

Dated: 30 /09/2021

The President/ Secretary, Mother Dairy CGHS Ltd.) Plot No.6, Sector-5, Dwarka, New Delhi-110075

Subject: Compliance of observation made in letter no ADO/DWK/70 dated 29/07/2020 in r/o The Mother Dairy Employees CGHS Ltd. located at Plot No.6 Sector-5, Dwarka,

Sir,

Please refer to email dated 23/09/2021 on the subject cited above. In this connection it is to inform you the inspection of above said premises has been carried out by the officer concerned of this department on 28/09/2021 to see the compliance of shortcomings communicated vide letter no ADO/DWK/90 Dated 29/07/2020.

During the course of inspection the fire fighting system was checked / operated and found in good working condition. The rectified shortcomings are as under:-.

- 1. Two ABC fire extinguishers provided at each floor.
- 2. First aid hose reel found functional.
- 3. MOEFA found functional.
- 4. Internal / yard hydrants found functional.
- 5. Fire pump at terrace found functional.
- 6. Draw off connection found repaired.
- 7. Exit signage found provided.

In view of above it revealed that the management have rectified all the shortcomings communicated vide letter dated 29/07/2020. The management is hereby advise to maintain the fire safety arrangements in good working order as seen during inspection. The management shall be responsible for any loss of property/ life due to nonfunctioning of the fire fighting systems / equipments.

Yours faithfully

Delhi Fire Service.

Copy to-

X. The CEO, BSES Rajdhani power Limited BSES Bhawan, Behind Nehru Place Bus Terminal

^{2.} The CEO, Varunalaya Building, Jhandewalan II, New Delhi, Delhi-110055.