

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No: F.6/DFS/MS/School/WZ/2021/535

Dated: - 04/10/2021

To

The Assistant Engineer (E)  
Sub-Div-1 Education Divn M1 (N),  
PWD GNCT, Govt. of Delhi,  
ITI Campus, Pusa, New Delhi

Sub.:- Regarding renewal of Fire Safety Certificate in r/o Sarvodaya Kanya Vidyalaya located at S.P. Road, Nangloi, New Delhi-10041.

Sir,

This is in reference of Email dated 13/08/2021 received in this department on the subject cited above. In this connection, it is to inform you that the school building have been inspected by the officer concerned of this department in presence of Mr. L.N Gupta (Contractor) on 15/09/2021 to check the fire safety arrangements provided in the building. During the inspection, it was also observed that the building complex is comprised of 02 blocks- Ground + three upper floors each. The following shortcomings have been observed:

1. Hose Reels nozzles are not provided.
2. Fire Pump head provided 26 m against requirement of 40 m head.
3. Overhead tank capacity 10,000 ltrs found empty.
4. Exit Signages are not adequate.
5. Electrical panel provided under the staircases to be removed.
6. Lift Shaft to be sealed by brick wall at each floor till lift car is not provided.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

(Atul Garg)

Director

Delhi Fire Service

Copy to: -

1. The Director of Education, NDMC, Civic Centre, Minto Road, New Delhi.

dc  
01/10/21