

Hand sanitize frequently-wearing of face mask –keep physical distance (02 gaj) to prevent from Covid -19

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F. 6/DFS/MS/NDZ/2021/ 100

Dated:- 14/01/2021

To

The Executive Engineer
North , MCD
Civic Centre , New Delhi

Sub: Regarding issuance of Fire Safety Certificate in r/o Auditorium , Music Dance and Drama Centre at 33 DDU Marg New Delhi.

Sir,

This has a reference to online ID. **10043140** dated 07.01.2021 on the subject cited above. In this regard, it is to inform you that the site was jointly inspected by ADO (CC) & DO (CD) of this department on dated 12.01.2021 along with representative of Owner/Occupier Sh. Anupam Bhatnager from building side, Sh. Atul Kumar JE, MCD, Sh.Mahesh Chandra , AE, MCD & Sh. Rahul Agrawal, Arch. and the following shortcomings were observed:-

1. Width of main staircase and alternate staircase is not provided as required i.e 1.5 meter.
2. Staircase serving to basement are not segregated at ground floor.
3. Width of door is not equal to staircase door.
4. Fire check door on the staircase is not provided in basement.
5. Electrical shafts are not sealed.
6. First aid hose reel is not provided.
7. Fire extinguishers are not installed as per IS 2190.
8. Smoke venting arrangement is not provided in basement.
9. Terrace pump of 450 LPM (02 Nos) is not provided as the basement area is more than 200 Sqm.
10. Access to terrace tank is not provided.
11. Exit and lift signages are not provided.

Further , it is also to inform that the building has not been constructed as per sanctioned/ approved plans.

In view of above, the case is rejected and Fire safety certificate cannot be issued due to above shortcomings.

Yours faithfully

(Atul Garg)
DIRECTOR

011-23410000




