

DFA  
C37

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE  
NEW DELHI-110001**

No.F6/DFS/MS/School/2021/ 560

Dated 11/10/2021

To,  
The Principal,  
M/s Sarvodaya Kanya Vidyalaya,  
Mandoli, Delhi 110093

Sub:- Regarding Issuance of Fire Safety Certificate in r/o Sarvodaya Kanya Vidyalaya,  
Mandoli, Delhi 110093.

Sir,

With reference to your email letter no. nil dated 07/04/2021 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view in presence of Mr. Ashok Verma, (H.O.S). During the course of inspection the following points / shortcomings were noticed in the school building comprised of ground plus three upper floors.

1. First-Aid hose reels provided but not functional.
2. A fire pump having 450 lpm output at 40 meters head provided at terrace but not functional.

In view of above, the school building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully

  
(Atul Garg)  
Director

Copy to:-

- 1) The Dy. Director of Education,  
B-Block, Yamuna Vihar,  
Delhi-110053