

A  
c-8  
c-7

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No.F6/DFS/MS/School/NDZ/2021 | 569

Dated: 14/10/2021

To

The Principal,  
Shaheed Bhai Bal Mukund,  
Govt. Sarvodaya Vidyalaya, Shankracharya Marg, Delhi-54.

**Sub:-** Regarding issuance of Fire Safety Certificate in r/o **Shaheed Bhai Bal Mukund, Govt. Sarvodaya Vidyalaya, Shankracharya Marg, Delhi-54**

Sir,

With reference to email dated 06.07.2021 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (SPM) from this department on 14.09.2021 in the presence of Mr. Amrender Singh (Civil contractor) & Mr. Vishal (electrical contractor) and it was observed that the school building is comprised of ground + 3 upper floors (New block). During the inspection following shortcomings were observed

1. All the halls at third floor shall have minimum two independent exits (doorways) of 1.5 m width.
2. Entry/exits to any hall should not be through the occupied area.


In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

  
(Atul Garg)  
Director

Delhi Fire Service  
Tel:-011-23414000

**Copy to:-**

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.
  2. Mr. Deepak Mishra, Assistant Engineer (E), PWD sub-Division4, Edu. Elect. Edn.1 Div. (N), Zakhira, Rama Road, Delhi-15.
- c/c   
13/10