

C 4

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No. F6/DFS/MS/School/WZ/2021/ 574

Dated: 18/10/2021

To,

Asst.Engineer,(E)
Edu. Sub-Divn M1-1, (N)
PWD, ITI Campus, Pusa,
New Delhi-110012.

Sub: - Regarding Issuance of Fire Safety Certificate in respect of Govt. Girls Secondary School Raghbir Nagar J.J. Colony New Delhi-110027(New Building School ID-15151030).


Sir,

This is in reference to your letter No. 54 (SPS School)/PWD Edu. Sub-Divn M1-1 (N) 2021-22/102 dated 09/08/2021, on the subject cited above. In this connection, it is to inform you that the School Building was inspected by the officer concerned of this department on 04/10/2021 in the presence of Sh. Nitin Panwar (Project Incharge) to check the workability of fire safety arrangements provided in the building. During Inspection it has been observed that the School building has Three Blocks all are interconnect, building is comprised of Ground +03 upper floors served by 03 staircases. Fire safety arrangements Such as First -Aid Hose reels, Over head water storage tank, Exit Signage's are provided. However the following Shortcomings were observed.

1. First-Aid Hose Reels are provided but not functional.
2. Terrace fire pump of capacity 900 LPM is provided but not functional & not on automode.
3. Building plans are not signed by the engineers of PWD.
4. Class room doors opening outward on the corridor create hindrance for evacuation.

In view of the above Shortcomings, the application for Issuance for Fire safety Certificate is rejected. The occupancy of the Building/premises in absence of requisites fire safety arrangements shall is at the risk and liabilities of the Owner/Occupier.

Yours Faithfully,


(Atul Garg)
Director
Delhi Fire service

Copy To: -

