GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE **NEW DELHI- 110001**

No. F6/DFS/MS/School/2021/SZ/ 592

Dated: 01/11/2021

6-35

To,

Assistant Engineer (E), Education (Maint.) Sub Division M1-1, PWD, ITI Campus, Pusa, New Delhi-110012.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Govt. Girls/Boys Sr. Sec. School, G-Block, Vikaspuri, New Delhi-110018.

Sir,

This has reference to your letter no.No. 54(SPS School) PWD Edu. Sub-Divn M1-1(N)2021-22/136 Date 10/09/21 on the subject captioned above. In this connection, it is to inform you that the above mentioned school premises was inspected by the officer concerned of this department on 25/10/2021 in the presence of Smt. Urmila Devi (Vice-Principal) to verify the compliance of vide department this communicated by already no.F6/DFS/MS/School/2019/SZ/3531 dated 13/06/2019 & F6/DFS/MS/School/2021/SZ/413 dated shortcoming 13/08/2021 and observed that shortcomings are still not rectified. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully

(Sunil Chawdhary) Dy. Chief Fire Officer

Copy to:-

- The Director of Education, Govt. of NCT of Delhi, Old Secretariat, 1. New Delhi-110054.
- The Principal, Govt. Girls/Boys Sr. Sec. School, 2. G-Block, Vikaspuri, New Delhi-110018

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2019/SZ To,

Dated: 13)06/19

2-21

Assistant Engineer (E), Education (Maint) Sub Divn M1-1, PWD, ITI Campus, Pusa, New Delhi-110012

Sub: - Regarding issuance of Fire Safety Certificate in r/o Govt. Girls/Boys Sr. Sec. School, G-Block, Vikas Puri, New Delhi-110018.

Sir.

S ..

This has reference to your Letter No. 54(SPS)SCHOOL/PWD Edu.Maint.DivnM1/2018-19/10 dated 18.03.19 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 17.05.19 to see the compliance of the requisite fire safety measures. Sh. H.S. Mishra (Estate Manager) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of four blocks namely A-Block, B-Block, C-Block & MP hall block. Block-A, Block-B & Block-c are having ground plus three upper floors & MP hall having ground floor only. The upper floors A block are served by single staircase having width 172 cms and the upper floors of B-Block are served by two staircases having width 172 & 172 cms and the upper floors of Block-C are served by single staircase having width 168 cms. The fire protection arrangements such as Fire Extinguishers, Hose reels, Overhead water storage tank having capacity 10000 ltrs in each block, Fire pumps of 450 LPM (02 no.'s) in each block, Exit signs etc. are provided in the building. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

- 1. The upper floors of Block-C are served by single staircase having width 168 cms against required two staircases having width 150 & 135 cms each from ground floor to terrace.
- 2. Door width is 115 cms (double doors) against required 120 cms in C block.
- 3. Hose reel system provided but not functional in Block-A and Block-B. Nozzles are
- 4. Fire pump having capacity 450 LPM (02 no.'s) provided in Block-A & Block-B but not functional.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithful (AT CHIEF FIRE OFFICER

Copy to:-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054

2. The Principal, Govt. Girls/Boys Sr. Sec. School, G-Block, Vikas Puri, New Delhi-18