

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No: F.6/DFS/MS/School/WZ/2021/ 60

Dated: - 11/02/2021

To

The Assistant Engineer (E),
Edu. Sub- Divn M1-1, (N),
PWD, ITI Campus, Pusa,
New Delhi- 110012.

Sub.: - Regarding issuance of Fire Safety Certificate in r/o Govt. Sarvodaya Kanya Vidyalaya School, ID-1617005 (Morning) & 1617227 (Evening), Ranholla, New Delhi- 110041.

Sir,

Please refer to your Letter No. 54(SPS School)/PWD Edu. Sub- Divn M1-1(N)/2020-21/54 dated 28.12.2020. on the subject cited above. In this connection, it is to inform you that the school building have been inspected by the officer concerned of this department in presence of Sh. Vijay Kumar Pandey (Estate Officer), on 27.01.2021 to check the fire safety arrangements provided in the building.

During the inspection, it was also observed that the building complex is comprised of old block and two new blocks- E & F. Old block is comprised of ground plus one upper floor and was issued 'Fire Safety Certificate' by this department vide letter No. F.6/DFS/MS/School/2018/WZ/2194 dated 27.09.2018. New Blocks are comprised of ground plus three upper floors each. No fire safety arrangements found provided in the new Blocks. However, following fire safety arrangements are required in New Block- E & F: -

1. First aid hose reel is required.
2. Terrace pump capacity 450 lpm is required.
3. Exit signages found missing at various places in both the blocks.
4. Fire extinguishers are not provided.
5. Overhead tank is provided but found empty.

In view of the above, 'Fire Safety Certificate' cannot be issued at this stage. You are requested to rectify the above-mentioned fire safety arrangements under intimation to this department.

Yours faithfully

(ATUL GARG)
DIRECTOR

Copy to: -

1. The Principal, Govt. Sarvodaya Kanya Vidyalaya School, Ranholla, New Delhi- 110041.
2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.

-for information please.