018

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/School/2021/ 6 5

Dated 22/11/21

To.

The Manager, S.B Public School E-Block, Khajoori Colony, Delhi-110094

Sub:- Regarding Issuance Fire Safety Certificate in S.B Public School located at E-Block, Khajoori Colony, Delhi-110094.

Sir,

With reference to your Email dated 18/10/2021 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view on dated 29/10/2021 in presence of Mr. R.K Chauhan, (Principal) of the School. The following points / shortcomings were noticed in the building comprised of ground plus two upper floors.

- 1. The Width of the staircase 1.50 meters wide are not provided.
- 2. Only 04 fire extinguishers provided in place of 09 fire extinguishers as required.
- 3. First-Aid hose reels (01 nos.) not functional at each floor at the time of inspection.
- 4. A fire pump having 450 LPM output at 40 meters head not provided.
- 5. Over head tank 2500 liter provided in place of 10,000 liter as required.
- 6. Exit signage not provided.

In view of above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully

4AtųI Gard) Director

Copy to:-

The Dy. Director of Education, B-Block, Yamuna Vihar Delhi 110053