

C-35

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001**

No.F6/DFS/MS/School/NDZ/2021/631

Dated: 07/12/2021

To

Vice Principal,  
Govt. Co-ed Sec. School,  
869/II, Kucha Kabil Attar Main Road,  
Chandni Chowk, Delhi (School ID no. 1208011).

**Sub:-** Regarding issuance of Fire Safety Certificate in r/o Govt. Co-ed Sec. School, located at 869/II, Kucha Kabil Attar Main Road, Chandni Chowk, Delhi (School ID no. 1208011).

Sir,

With reference to your email letter dated 17.11.2021 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (SPM) from this department on 24.11.2021 in the presence of Dr. Puran Singh, (Vice Principal) and it was observed that the building is comprised of ground + mezzanine +3 upper floors. The School is running at 1<sup>st</sup> floor to 3<sup>rd</sup> floor only. During the inspection following shortcomings were observed:-

1. Alternate staircase having a minimum width of 75 cms should be extended up to 3<sup>rd</sup> floor as teaching activities were found at 3<sup>rd</sup> floor also.
2. Entry/exits to any class room should not be through the occupied area.
3. First-aid-hose reels found not provided.
4. Fire pump having capacity 450 LPM & head 40 mtrs. found not provided.
5. Overhead tank capacity 10,000 liters for firefighting found not provided.
6. Exit signages found not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

  
06/12/21

(Dr. S.K. Tomar)  
Dy. Chief Fire Officer  
Tel: 011-23412025

**Copy to:-**

The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.

ok Dh  
06.12.21