

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F6/DFS/MS/School/2021/ 67

Dated: 12 /02/2021

To

The Principal,  
Guru Harkishan Public School,  
Gurudwara Road, near Gurudwra,  
Karol bagh, New Delhi.

**Sub: Regarding issuing of FSC in r/o Guru Harkishan Public School. Gurudwara Road, near Gurudwra, Karol Bagh , New Delhi.**

Sir,

This has reference to your E-mail< Vivek Dhamija68@gmail.com> dated 10.12.2021 on the subject cited above. In this regard, it is to inform you that the site was inspected by officer concerned of this department on 03.02.2021 in the presence of Sh. Jaswinder Singh and the following shortcomings are observed.

1. Alternate staircase of .75 m is not provided in the basement.
2. Smoke management system is not provided in basement.
3. Fire Extinguishers are not provided as per IS 2190.
4. Sprinkler system is required in basement, if the area is more than 200 Sqm.
5. Exit Signages are not provided.
6. Over head tank of 10,000L liter capacity is provided against the requirements 15,000 liter (if basement area is more than 200 Sqm). \
7. Also to submit undertaking that no correspondence with Delhi Fire Service was undertaken in past with respect to this premises.

In view of above, fire safety certificate (FSC) cannot be issued.

Yours faithfully,

(Atul Garg)

DIRECTOR

Delhi Fire Service

Copy to:-

The Director (Education),  
Govt. of NCT, Old Sectt.  
Delhi - 54.

an