

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No.F6/DFS/MS/School/2021/ 79

Dated 17/02/2021

To,

The Principal,  
EDMC Primary School,  
Brahampuri old, Gali. No.12,  
Delhi-53

**Sub:- Request for issuing a Fire Safety Certificate.**

Sir,

With reference to your e-mail ID:- hos1152127@gmail.com dated 21/01/2021 on the subject cited above, it is informed that officer concerned of this department inspected the school from fire safety point of view in presence of Mrs. Geeta Sharma, Principal of the School on dated 10/02/2021. The School building comprises of ground plus two upper floors. During the course of inspection following observations were made:-

1. The premises is not accessible to fire engines.
2. A fire pump with 450 liters per minute discharge at 40 meters head (4kgf/sq.cm.) is required be Provide at terrace level.
3. Firefighting system which has been provided in the building, was not functional at the time of Inspection.

In view of the above, the school building cannot be considered for issuance of Fire Safety Certificate at this stage.

Yours Faithfully,

  
12/2/21

(Dr. S. K. Tomar)  
Dy. Chief Fire Officer

Copy to:-

The Director of Education, EDMC  
Udyog Sadan, Plot No. 419, FIE,  
Patparganj Industrial Area, Delhi-92