

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No. F6/DFS/MS/2022/SZ/CGHS/699

Dated: 29/03/2022

To,-

Sh. Alok Gupta (President) < Sujaggsaji@yahoo.com >
IDC CGHS,
Plot No 8C, Sector – 11,
Dwarka, New Delhi – 110075

Subject: Renewal of Fire Safety Certificate in r/o IDC CGHS, Plot No 8C, Sector – 11,
Dwarka, New Delhi – 110075.

Sir,

Please refer to letter no Nil Dated-24/02/2022 on the subject mentioned above. In this connection it is submitted that that the above said premises was visited by the officer concerned of this department on 28/02/2022 to see the compliance of the shortcomings communicated vide this office letter no. F6/DFS/MS/CGHS/2019/SZ/1280 dated 15/03/2019 (copy enclosed) and found that the shortcomings are still not complied. You are requested to comply the shortcomings under intimation with this department.

In view of the above FSC from fire safety point of view cannot be considered at this stage.

Yours faithfully,

Enclosed: - As Above


(Anil Garg)
Director,
Delhi Fire Service.

Copy to: - 1. Joint Director, DDA, Vikas Sadhan INA, New Delhi

C-40

1108

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No.F6/DFS/MS/CGHS/SZ/2019/SZ/ 1280

Dated: 15/03/19

C-81

To,

Sh. S.P GARG,
M/S DESIGN'N'DESIGN,
S-4 Anupam Plaza, I.I.T Crossing,
Hauz Khas, New Delhi-110016.

Subject: - Issuance of Fire Safety Certificate in r/o IDC CGHS Ltd. Plot No. 8C, Sector-11
New Delhi-110075.

Sir,


This is in reference to your letter no. DND/GH/262/19 dated 10.01.2019 on the subject cited above. In this connection it is to inform you that the above said residential building have been inspected by the officer concerned of this department on 18.2.2019 in presence of Sh. N M Mittal (Member) to check the workability of fire safety systems provided in the building as per fire safety directives issued vide this department letter no. F6/DFS/MS/BP/2017/58 dated 2.3.2017.

During the course of inspection following shortcomings have been observed:-

1. Width of roads all around the building for Fire tender movement is 4.80 & 5 Mtrs. at two sides of the building instead of required width 6 Mtrs.
2. Width of the staircases is 1.20 Mtrs. at some points instead of required width 1.25 Mtrs.
3. One ABC fire extinguisher is provided instead of two at each level in all blocks.
4. Exit sign not provided at some places.

In view of the above shortcomings Fire Safety Certificate cannot be granted. You are advised to rectify the above shortcomings under intimation to this department for taking further necessary action.

Yours faithfully,


Chief Fire Officer(H.Q)
Delhi Fire Service


Copy to:-

1. The Dy. Director Bldg. (L&I) DDA, Vikas Sadan INA New Delhi-110023.
2. President, IDC CGHS Ltd. Plot No. 8C, Sector-11, Dwarka, New Delhi.