

C19

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2022/WZ/ 149

Dated: 29/03/2022

To,

The Principal,
M C Primary School,
J.J. Colony, B-Block,
Sawda, Delhi-110081.

Sub: - Regarding issuance of Fire Safety Certificate in r/o M C Primary School, J.J.Colony,B-Block, Sawda, Delhi-110081.

Sir,

This has reference to your letter no. nil dated 17.02.2022 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 16.03.2022 to see the compliance of the requisite fire safety measures. Sh. Hardayal Singh (Teacher Incharge) was present at the time of inspection.

During the course of inspection it was observed that school building was comprised of Ground floor plus two upper floors. Your request of issue of FSC is rejected as the following shortcomings were observed:-

1. Width of staircases found 1.50 m & 1.25 m against required width of 1.50 m each.
2. Gate width found 3.60 m against required width of 4.5 m.
3. First-Aid Hose Reel not provided.
4. Terrace level fire pump of 450 lpm capacity not provided.
5. Over Head Water tank of 10,000 ltrs capacity not provided.
6. Exit Signage not provided.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for issuance of Fire Safety Certificate.

Yours Faithfully,

(Anur Garg)
Director

Delhi Fire Service

ole R

Copy to:-

1. Director of Education, NDMC, Civic Center, New Delhi.