C66

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/EH/WZ/2022/ 279

Dated: 01/04/2022

Director

To

The Joint Commissioner of Police (Lic.), 1<sup>st</sup> Floor, Police Station Defence Colony, New Delhi.

Sub.:- Inspection report for issuance of Fire Safety Certificate in r/o M/s. Bellagio Restaurant located at 13,14, Community Centre, Ashok Vihar Phase-II, Delhi- 110052.

Sir,

Please refer to the online application No. 2022031703707 received through MHA portal, on the subject cited above. In this connection, it is to inform you that the aforesaid restaurant has been inspected by the officers concerned of this department, in presence of Sh. Vikas Gupta(manager) on 22.03.2022 to check the required fire safety & means of escape measures. During inspection, it has been observed that the said restaurant is located at ground, mezzanine, first, second & third floor of a building comprised of basement, ground, mezzanine, first, second, third & terrace floor with seating arrangements and kitchen. The said restaurant is served by two staircases having width 1.5 mts each and one lift. Fire fighting arrangements such as overhead tank capacity 10,000 lts, fire pumps capacity 2280 LPM (Main), 2280 LPM (Standby) & 180 LPM provide on the terrace, internal hydrant, first aid hose reel, MOEFA, etc. found provided. However, the following shortcomings were observed:-

- 1. Width of staircase is 1.5 mts each against requirement of 2.0 mts & 1.5 mts.
- 2. Width of exit doors is 1.5 mts & 1 mt against requirement of 2.0 mts & 1.5 mts
- 3. Diesel pump is not provided.
- 4. Underground water tank capacity 1,00,000 lts is required.
- 5. Basement floor & doors opening from kitchen to the staircase are not segregated with Fire Check Door.
- 6. 02 nos. of CO<sub>2</sub> & ABC type fire extinguishers are not provided at each floor.
- 7. Exit signages are not provided.
- 8. Smoke management system is not provided
- 9. Kitchen and seating arrangement shall be removed from terrace floor.

In view of the above shortcomings, the application for grant of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite Fire safety arrangements shall be at the risk and liability of the owner/occupier. The licensing authority /statutory authority may take suitable necessary action as deemed fit.

Copy to: -

- 1. The Deputy Health Officer, North Delhi Municipal Corporation, Keshavpuram Zone,
- 2. Sh. Gurdeep Singh, Owner/occupier, M/s. Bellagio Restaurant located at 13,14, Community Centre, Ashok Vihar Phase-II, Delhi- 110052.