## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F.6/DFS/MS/RESIDENTIAL/NDZ/2022/ Sog

Dated: 08 .04.2022

To

C

Assistant Engineer (E). PWD NES ESD-4/M2533, Qtr No. 160 DA Flats, Karkardooma, Delhi- 110092.

Sub:- Regarding Fire Safety Certificate of Old Age Home, Kanti Nagar, Shanti Mohalla, Gandhi Nagar, Delhi.

Sir,

This has a reference to your letter no. 5(25)/A.E.(E)/PWD/NES ESD-4/2021-22-68 dated 17.03.2022 on the subject cited above. In this connection, it is to inform you that above said premises was inspected by the officer concerned of this department on dated 31/03/2022 in the presence of Sh. YPS Sharma AE(E)/PWD to see the compliance of Fire Safety recommendations issued by this department vide letter No. F6/DFS/MS/BP/2017/63 Dated 08/03/2017 and observed that building comprised of stilt and five upper floors (Residential Occupancy).

Following shortcomings were observed during time of inspection.

- 1. Automatic sprinkler system not provided in the stilt floor.
- 2. Hose Box not provided at each floor.
- 3. A Fire Pump of 2280 LPM capacity and a Standby Diesel pump of same capacity and a jockey pump of 180 LPM capacity are not provided.
- 4. Capacity of underground tank 40,000 liters is provided against requirement of 1,00,000 ltrs. Measurement of underground tank is also required for calculating capacity of tank.
- 5. Exit Signages, pressurization of lift lobby and lift shaft, fireman's grounding switch and lift signages not provided.
- 6. Fire Control Room also not provided.

In view of above your application for issuance of Fire Safety Certificate is rejected under rule 35(3) of Delhi Fire Service Act 2007 & Rules 2010. You are requested to apply for Fire Safety Certificate after rectification of above mentioned shortcomings under intimation to this department for taking necessary action in this matter.

Yours faithfully,