

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F6/DFS/MS/School/2022/SZ/ 164

Dated: 07/04/2022

C-36

To,

The Vice-Principal, SKV Ghumanhera, New Delhi-110073.

Sub:-Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o SKV Ghumanhera, New Delhi-110073.

Sir/Madam,

This has reference to your letter no. SV/GH/2022/3189 dated 08/03/2022 on the subject captioned above. In this connection, it is to inform you that the above mentioned building/premises was inspected by the officer concerned of this department on 30/03/2022 in the presence of Sh. Jaipal (Estate Manager) to verify the compliance of shortcoming already communicated by this department vide letter no. F6/DFS/MS/School/2019/SZ/5672 dated 19/09/2019 & F.6/DFS/MS/School/2021/SZ/371 dated 27/07/2021 and observed that shortcomings are still not rectified except point no. 2, 6. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully (Sunil Chawdhary) Dy.Chief Fire Officer

Copy to:-

 The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.
(With a request to take further action as school does not have fire NOC)

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2019/SZ /5692

Dated: 19/9/19

UTV 7

To,

The Principal, Govt. Girls Sr. Sec. School, Ghumanhera, New Delhi-110073

Sub: - Regarding issuance of Fire Safety Certificate in r/o Govt. Girls Sr. Sec. School, Ghumanhera, New Delhi-110073

Sir/Madam,

This has reference to your Letter No. 1085/2019 dated 26.07.2019 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 23.08.2019 to see the compliance of the requisite fire safety measures. Smt. Sunita (Vice-Principal) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of ground plus one upper floor and MP hall being used as Auditorium. The upper floor is served by three staircases having width 150 cms each. The building is approachable to fire fighting appliances. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcoming was observed:-

- 1. The School is not approachable through gate having width 4.5 meters.
- 2. Class room door width is 95 cms against required width of 100 cms and door width of Auditorium hall is 180 cms against required width of 200 cms each.
- 3. Hose reel system for auditorium not provided.
- 4. Terrace fire pump having capacity 450 LPM not provided for auditorium.
- 5. Overhead water storage tank of 5,000 ltrs capacity not provided for hose reel system for auditorium.
- 6. Illuminated exit signs not provided in auditorium.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Valut A (ATUN CHIEF FIRE OFFICER

Copy to:-

Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

(with a request to take further action as school does not have fire NOC)