

C-22

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/SZ/2022/ 157

Dated: 05/04/2022

To

The Chairman,
Don Vasco Convent School,
WZ-238, Shiv Nagar, Jail Road, New Delhi-110058.


Sub.: - Regarding renewal of Fire Safety Certificate in r/o Don Vasco Convent School, WZ-238, Shiv Nagar, Jail Road, New Delhi-110058.

Sir,


Please refer to your e-mail dated 08.03.2022 received through e-mail ID <mkkaushik52@gmail.com> on the subject cited above. In this connection, it is to inform you that the aforesaid school building have been inspected by the officer concerned of this department in presence of Sh. Mahesh Kaushik, Chairman of the School, on 24.03.2022 to check the status of the shortcomings pointed out by this department vide letter No. F.6/DFS/MS/School/2019/SZ/7847 dated 24.12.2019, but no improvement was observed as seen during the course of inspection and this department has already issued a letter in this matter vide this office letter No. F.6/DFS/MS/School/2022/SZ/80 dated 23.02.2022.

In view of the above, 'Fire Safety Certificate' cannot be renewed at this stage. You are requested to rectify the above-mentioned fire safety arrangements under intimation to this department.

Yours faithfully



(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service



Copy to: -

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

(with a request to take further action as school does not have fire NOC)

219

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001

No. F6/DFS/MS/School/2022/SZ/ 80

Dated: 23/02/2022

To,


The Manager,
Don Vasco Convent School,
WZ-238, Shiv Nagar, Jail Road, New Delhi-110058.

Sub:-Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Don Vasco Convent School, WZ-238, Shiv Nagar, Jail Road, New Delhi-110058.

Sir,

This has reference to your letter no. Nil dated 06/02/2022 on the subject captioned above. In this connection, it is to inform you that the above mentioned building/premises was inspected by the officer concerned of this department on 10/02/2022 in the presence of Sh. Mahesh Kaushik to verify the compliance of shortcoming already communicated by this department vide letter no. F6/DFS/MS/School/2019/SZ/7847 dated 24/12/2022 and observed that shortcomings are still not rectified. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully


(Sunil Chawdhary)
Dy. Chief Fire Officer

Copy to:-

1. The Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi-110054.
(With a request to take further action as school does not have fire NOC)

C-16

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2019/SZ 17847

Dated: 24/12/19

To,

The Principal,
Don Vasco Convent School (recognized),
WZ-238, Shiv Nagar, Jail Road, New Delhi-110058.

Sub: - Regarding issuance/renewal of Fire Safety Certificate in r/o Don Vasco Convent School (recognized), WZ-238, Shiv Nagar, Jail Road, New Delhi-110058.

Sir,

This has reference to your Letter No. DVCS/2019 dated 03.10.2019 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 03.12.2019 to see the compliance of the requisite fire safety measures. Smt. Kaushik (Principal) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of ground floor plus three upper floors was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2016/SZ/1817 dated 23.12.2016. Now three new rooms have been constructed on third floor. The upper floors are served by two staircases having width 100 & 100 to 70 cms. The school building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

1. The upper floors are served by two staircases having width 100 & 100 to 75 cms against required two staircases having width 150 cms each from ground floor to terrace.
2. Corridor width is 230 to 80 cms against required 150 cms.
3. Door width is 90 cms against required 120 cms in three additional rooms on third floor.
4. Required fire extinguishers are not provided. Eight fire extinguishers of DCP type/CO₂ type 2.5 Kg Capacity each are require to be provided.
5. Hose reel system not provided on third floor.
6. Terrace fire pump of 220 LPM capacity provided against required 450 LPM capacity.
7. Over head water storage tank of 5,000 ltrs capacity provided against required 10,000 ltrs capacity.
8. Exit signs are missing at number of places.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,



(ATUL DARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to:-

Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi - 110054

(with a request to take further action as school does not have fire NOC)


9/12/19