

C 53

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE  
NEW DELHI – 110001**

NO. F6/DFS/MS /SZ/2022/ School/173

DATED: 13/04/2022

To,

Mrs. Mary Gemna Lakra <skvsector1@gmail.com>  
Sarvodaya Kanya Vidhalaya, Block 1, 3 & 4,  
Pocket – 7, Sector – 1, Dwarka,  
New Delhi – 110045.

Subject: Renewal of Fire safety Certificate from fire safety & means of escape point of view in r/o Sarvodaya Kanya Vidhalaya, Block 1, 3 & 4 Located at Pocket – 7, Sector – 1, Dwarka, New Delhi – 110045.

Sir,

Please refer to Email dated 08/03/2022 on the subject mentioned above. In this connection it is submitted that that the above said premises was re inspected by the officer concerned of this department on 29/03/2022 to see the compliance of the shortcomings communicated vide this office letter no. F6/DFS/MS/School/SZ/2020/504 dated 13/05/2020 and found that the shortcomings are still not fully complied. You are requested to comply the shortcomings under intimation with this department.

In view of the above FSC from fire safety point of view cannot be considered at this stage.

Yours faithfully,



Sunil Chaudhary  
(Dy. Chief Fire Officer)  
Delhi Fire Service

Copy to:-

1. Directorate of Education Old Secretariat Delhi – 110054

AD OC  
13/4/22

07/69

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001**

No F6/DFS/MS/School/2020/SZ/ 524  
To

Dated 13/5/2020

Ms. Ashish Grover (HOS)  
Sarvodaya Kanya Vidhalaya  
Sector-1, Pocket-7,  
Dwarka, New Delhi-110045.

Subject - Renewal of Fire Safety certificate in r/o Sarvodaya Kanya Vidhalaya, Sector-1  
Pocket-7, Dwarka, New Delhi-110045

Madam,

Please refer to your letter no SKV/SEC-1/PKT-7/2020/82 dated 27.12.2020 on the subject cited above. In this regard this is to inform you that the said school building was inspected by the officer concerned of this department on 21.2.2020 in presence of Sh. Sunil Dagar (Estate Manager) to see the workability/functionality of fire safety measures provided in the building.

During the course of inspection, it has been observed that the said School premises consists of 5 Blocks comprised of Ground plus one upper floor & a MP Hall.

During inspection following shortcomings have been observed -

1. On Block No. 1, 3 & 4 LGS roof is erected which shall be removed.
2. Exit signage not provided at appropriate places.

In view of the above shortcoming, Fire Safety Certificate cannot be renewed/granted at this stage. You are advised to rectify the above said shortcomings under intimation to this department for taking further necessary action.

Yours faithfully,

*(Signature)*  
o/c (Atul Garg)  
Director

Copy to:-

1. Director (Education), GNCT of Delhi, Old Secretariat, Delhi.
2. The Principal, Govt. Boys Sr. Secondary School, Sector-1, Pocket-7, Dwarka, New Delhi-110045.