

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/Hospital/2022/NDZ/ 887

Dated: 22/04/2022

To

The Medical Superintendent,
Shanti Mukand Hospital, 2, Institutional Area,
Vikas Marg Extn., Delhi- 110092.

Subject:-Inspection report in r/o Shanti Mukand Hospital, 2, Institutional Area, Vikas Marg Extn., Karkardooma, Delhi110092.

Sir,

Please refer to your letter No. SMH/Admn/2022/8709 dated 03/03/2022, on the subject cited above, in this regard, it is to informed you that the premises was inspected by the officer concerned of this department to see the compliance of office letter no. F6/DFS/MS/Hospital/2020/NDZ/2960 dated 04/12/2020 and observed following points.

1. PA System provided but still not audible in basement and having poor quality.
2. Detectors and MCP provided in lift room but found non functional.
3. Hose reel hose still not covering the whole area viz. required one additional down comer to cater this area.
4. smoke management system provided in basement but found non functional.

In view of above, Fire Safety Certificate can not be considered at this stage.

You are requested to apply for renewal of Fire Safety Certificate after rectification of above mentioned shortcomings under intimation to this department for taking necessary action in this matter.

Yours faithfully,


(ATUL GARG)
DIRECTOR.