

244

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

No. F.6/DFS/MS/NDZ/2022/School/185

Dated: 20/04/2022

To

The Principal,  
Vanasthali Public School,  
Near Ruchika Petrol Pump, Mayur Vihar Ph-III,  
Delhi-110096.

**Sub:- Reg Fire Safety Certificate in r/o Vanasthali Public School Near Ruchika Petrol Pump, Mayur Vihar Ph-III Delhi-110096.**

Sir,

With reference to your E-mail dated 12/04/2022 on the subject above it is to inform you that the premises was already visited by the officer concerned of this department on dated 17/03/2022 in the presence of Mr. Mahesh Sharma (Admn.) and observations/shortcomings were sent by this department vide letter No. F6/DFS/MS/School/2022/NDZ/138 Dated 25/03/2022 (copy enclosed).

You are advised to apply for renewal of Fire Safety Certificate after rectification of shortcomings under intimation to this department for taking necessary action in this matter.

Yours faithfully.

  
19/4/22

(Dr. S.K. Tomar)  
Dy. Chief Fire Officer

 o/c

c-38

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/Restaurant/2022/NDZ/ 138

Dated: 25/03/2022

To

Mrs. Sonia Khanna (Principal),  
Vanasthali Public Sr. Sec. School, Mayur Vihar,  
Ph- III, Near Ruchica Petrol Pump, Delhi-110096.

**Sub.:- Regarding issuance of Fire Safety Certificate in r/o M/s Vanasthali Public Sr. Sec. School,  
Mayur Vihar, Ph- III, Near Ruchica Petrol Pump, Delhi-110096.**

Sir,

With reference to your Letter No. Nil dated 21/02/2022 on the subject cited above, the officer concerned of this department has carried out the inspection of the premises from fire safety point of view in presence of Mr. Mahesh Sharma (Admn.) on dated 17/03/2022. The building comprise of ground plus three upper floors. following shortcomings were observe during the time of inspection.

1. First Aid Hose reel and down comer were provided but not functional.
2. Fire Pump is provided but found non functional.
3. Overhead tank of 6000 ltr. capacity is provided against requirment of 10000 liters.
4. Exit signages found removed.
5. Tin Shed Rooms on the terrace should be removed which are used as school purpose.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected under sub rule (3) of rule 35 of DFS Act 2007 and Rules 2010. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. you are requested to apply after rectification of above mentioned shortcomings under intimation to this department.

Yours faithfully,

  
25/3/22

**(Dr. S.K. Tomar)**  
**Dy. Chief Fire Officer**

Copy to:-

Director of Education, Old Secretariat, Delhi-110054.

