

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001**

No. F6 /DFS/MS/Business/SZ/2022

972

Dated:

02/05/2022

To

M/s Institute of Electronics and Telecommunication Engineering,  
No. 2, Institutional Area, Lodhi Road,  
New Delhi-03.

Sub: - Regarding grant of Fire Safety Certificate in r/o **M/s Institute of Electronics and Telecommunication Engineering No. 2, Institutional Area, Lodhi Road, New Delhi-03.**

Sir,

With reference to your letter no. IETE/ADMIN/2022 dated 21.03.2022 on the subject cited above, it is informed that the said building was inspected by a team of officers from this department on 13.04.2022 in the presence of Mr. Harish (Dy. Secretary) and it was observed that the building is comprised of Basement + Ground + 05 upper floors (double height auditorium at 1<sup>st</sup> floor). During the inspection the following shortcomings were observed: -

1. Hose reels found non functional.
2. Smoke & heat detector found non functional.
3. MOEFA found non functional.
4. Automatic sprinkler system found non functional in basement and need to be extended in left out area.
5. Internal hydrant system found non functional.
6. Fire pumps found non functional.
7. Exit signages are not adequate.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Atul Garg)  
Director

Delhi Fire Service