

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

No.F6/DFS/MS/School/SZ/2022/911

Dated: 09/05/2022

To

The Principal,
Kapil Model School,
C-I – 57 & 58, Sangam Vihar, New Delhi-62.

Sub: - Regarding renewal of Fire Safety Certificate in r/o Kapil Model School located at C-I – 57& 58, Sangam Vihar, New Delhi-62.


Sir,

With reference to your letter no. KMS /FIRE NOC/2022 dated 31.03.2022 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 22.04.2022 in the presence of manager and it was observed that the school is running at ground and 1st floor of the building which is comprised of Ground + 02 upper floors. During the inspection following shortcomings were observed:-

1. The required road width of 6.0 meters is not available for accessibility of a standard fire engine.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,



(Sunil Chawdhary)

Dy. Chief Fire Officer
Delhi Fire Service

g/c [Signature] 02/5/22

Copy to:-

The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.